


Existing Façade Conditions at 6117 Monona Drive



**View from street at the South-East edge of property—
BEFORE**



**View from lower parking lot. Note retaining wall that is
falling down and steep slope to upper parking lot**



View from street across the parking lot




View looking up the hill at the sign

Proposed Façade Improvement Changes at 6117 Monona Drive



Creta stone steps—smooth concrete tread w. rock-face riser



Fountain to be in the bed near the front door



Unilock Brussels Block concrete Pavers for the walkway



Unilock Brussels dimensional for pillars and planter



Wall stone choices. Limestone "boulders"

5/4/2012

Proposed Plantings for Façade Improvement Changes at 6117 Monona Drive

Shrubs and trees to be used in plan



Existing shrubs along sidewalk



Sidewalk planting at Wisconsin Nurses Assn.



*Bur Oak Landscapes
6117 Monona Dr., Ste 3
Monona, WI 7-29-11*